

Village Of Huntington Bay
Catch Basin Inventory
MS4 Inspection and Maintenance Report

Drainage #	Location discription	Latitude	Longitude	drainage type	3/17-3/18	3/17-3/18	Estimated Volume Removed	Comment
					Inspection date	Clean out date		
V-1	86 East Shore Road	40 53.6369 N	73 25.1335 W	May be connected to Outfall #337 (8" drain)				FABCO FILTER INSTALLED
V-2	86 East Shore Road	40 53.6369 N	73 25.1335 W	May be connected to Outfall #337 (8" drain)				FABCO FILTER INSTALLED
V-3	86 East Shore Road	40 53.6369 N	73 25.1335 W	May be connected to Outfall #337 (8" drain)				FABCO FILTER INSTALLED
V-4	SE intersection of East Shore Road and Kaness Lane	40 53.7779 N	73 25.2078 W	May be connected to Outfall #194 (14 inch PVC)				
V-5	NE intersection of East Shore Road and Kaness Lane	40 53.7779 N	73 25.2078 W	May be connected to Outfall #194 (14 inch PVC)				
V-6	SW intersection of East Shore Road and Kaness Lane	40 53.7779 N	73 25.2078 W	May be connected to Outfall #194 (14 inch PVC)				
V-7	NW intersection of East Shore Road and Kaness Lane	40 53.7779 N	73 25.2078 W	May be connected to Outfall #194 (14 inch PVC)				
V-8	138 East Shore Road Curb Inlet partial paved over	40 53.9295N	73 25.3380 W	Pond Discharge overflow				
V-9	136 East Shore Road (East Side)	40 53.9704 N	73 25.5380 W					
V-10	136 East Shore Road (West Side)	40 53.9704 N	73 25.5380 W					
V-11	158 East Shore Road (East Side)	40 53.9660 N	73 25.4339 W	Discharges to leaching bioswale east side of road				
V-12	158 East Shore Road (West Side)	40 53.9660 N	73 25.4339 W	Discharges to leaching bioswale east side of road				
V-13	180 East Shore Road (West Side)	40 54.0460 N	73 25.5723 W	needs a service and does not appear to discharge to outfall				
V-14	192-194 East Shore Road (West Side)	40 54.0963 N	73 25.6436 W	May be connected to outfall 129 or 130 (5 inch & 12 inch)				
V-15	200 East Shore Road (West Side)	40 54.1023 N	73 25.6932 W	May be connected to outfall 129 or 130 (5 inch & 12 inch)				
V-16	6 Woodland Drive (West Side)	40 54.1249 N	73 25.7241 W	Leaching System connected				
V-25	330 Bay Avenue	40 54.1910 N	73 25.7759 W	Leaching System Connected				
V-26	330 Bay Avenue	40 54.1910 N	73 25.7759 W	Leaching System Connected				
V-27	311 Bay Avenue (East Side adjacent to pillars)	40 54.1674 N	73 25.6965 W	Leaching System Connected				
V-28	311 Bay Avenue at intersection with Wincoma	40 54.1674 N	73 25.6965 W	Leaching System Connected				
V-32	9 Harbor Hill Road (middle of road round inlet)	40 54.0830 N	73 25.4741 W	Leaching System Connected				
V-35	219 Bay ave	40 55.179 N	73 25.864 W	Leaching System Connected				
V-40	299 Bay ave at intersection with Harbor View dr	40 54.166 N	73 25.625 W	Leaching System Connected				
V-41	299 Bay ave at intersection with Harbor View dr	40 54.166 N	73 25.625 W	Leaching System Connected				
V-79	161 Bay Avenue	40, 53.948 N	73, 25.089 W	2X4 Catch Basin				
V-80	161 Bay Avenue	40, 53.948 N	73, 25.089 W	2X4 Catch Basin				
V-81	Vineyard Road	40, 54.215 N	73, 24.861W	2X4 Catch Basin				
V-82	Vineyard Road	40, 54.202 N	73, 24.861 W	2X4 Catch Basin				
V-83	33 Sydney	40, 54.169 N	73, 24.865 W	2X4 Catch Basin				
V-84	33 Sydney	40, 54.165 N	73, 24.865 W	2X4 Catch Basin				
V-85	289 Vineyard	40, 54.134 N	73, 24.866 W	2' Diameter Grate				
V-86	289 Vineyard	40, 54.134 N	73, 24.866 W	2' Diameter Grate				
V-87	289 Vineyard	40, 54.117 N	73, 24.871 W	2X4 Catch Basin				
V-88	285 Vineyard	40, 54.093 N	73, 24.872 W	2X4 Catch Basin				
V-89	Vineyard And Cedar	40, 54.082 N	73, 24.866 W	2' Diameter Grate				
V-90	Vineyard And Cedar	40, 54.078 N	73, 24.863 W	2' Diameter Grate				
V-91	Bay Ave between 126-128	40 54.080 N	73 24.869 W	type 1				
V-92	Bay Ave between 126-128	40 53.817 N	73 24.948 W	type 1				
V-93	Bay ave across from 99	40 53.726 N	73 24.894 W	type 1				
V-94	Kaiser Hill & Vineyard intersection SE	40 53.989 N	73 24.896 W	type 1				
V-95	Kaiser Hill & Vineyard intersection SW	40 53.993 N	73 24.903 W	type 1				
V-96	Vineyard & Kaiser Hill intersection NE #1	40 54.088 N	73 24.881 W	type 1				
V-97	Vineyard & Kaiser Hill intersection NE #2	40 54.010 N	73 24.881 W	24" DIA GRATE				
V-98	Vineyard & Kaiser Hill intersection point of curb	40 54.000 N	73 24.878 W	24" DIA GRATE				
V-99	Vineyard & Kaiser Hill intersection SE #1	40 53.990 N	73 24.879 W	type 1				
V-100	Vineyard & Kaiser Hill intersection SE #2	40 53.988 N	73 24.877 W	type 1				
V-101	Drainage parcel grate #1	40 53.993 N	73 24.873 W	24" DIA GRATE				
V-102	Drainage parcel grate #2	40 53.995 N	73 24.873 W	24" DIA GRATE				
V-103	Drainage parcel grate #3	40 53.989 N	73 24.875 W	24" DIA GRATE				
V-104	Vineyard & Kaiser Hill intersection SW	40 53.980 N	73 24.887 W	type 1				
V-106	Vineyard #281 #1 closest to Kaiser Hill	40 54.013 N	73 24.892 W	24" DIA GRATE				
V-107	Vineyard #281 #2 furthest from Kaiser Hill	40 54.021 N	73 24.883 W	24" DIA GRATE				

V-108	Vineyard across from #107	40 54.019 N	73 24.879 W	24" DIA GRATE			
V-109	Vineyard between 283 & 285	40 54.069 N	73 24.878 W	type 1			
V-110	Vineyard south of the Police station	40 53.850 N	73 24.804 W	30" X 48" GRATE			
V-111	Vineyard #227	40 53.786 N	73 24.778 W	47" CURB INLET CB			
V-112	Vineyard #230 across from #227	40 53.785 N	73 24.769 W	30" X 48" GRATE			
V-113	Taylor intersection of Vineyard #230	40 53.785 N	73 24.765 W	type 1			
V-114	Vineyard #227 leftside looking at it	40 53.771 N	73 24.766 W	type 1			
V-115	Vineyard #228 corner of Taylor	40 53.769 N	73 24.755 W	type 1			
V-119	Sydney #10 corner & Locust lane	40 54.175 N	73 24.582 W	26" X 26" GRATE			
V-120	Locust lane infront of #1 Sydney	40 54.190 N	73 24.581 W	24" DIA GRATE			
V-121	Locust lane #17 infrom of utility pole	40 54.006 N	73 24.565 W	24" DIA GRATE			
V-122	Locust lane #7 next fire hydrant	40 53.845 N	73 24.529 W	type 1			
V-123	Bay rd just west of Locust Lane	40 53.756 N	73 24.521 W	type 1			
V-124	Bay rd about 120' west of Locust Lane	40 53.749 N	73 24.542 W	type 1			
V-125	Vineyard #225	40 53.745 N	73 24.745 W	30" X 48" GRATE			
V-126	Cedar & Taylor Island	40 54.067 N	73 24.770 W	24" DIA GRATE			
V-127	Cedar & Taylor #45	40 54.064 N	73 24.770 W	30" X 48" GRATE			
V-128	Cedar & Taylor #43	40 54.067 N	73 24.774 W	30" X 48" GRATE			
V-174	NW corner of Vineyard and Bay rd	40 53.711 N	73 24.702 W	type 1			
V-175	SW corner of Bay ave and Castle Harbor rd	40 53.683 N	73 24.886 W	Curb inlet			
V-176	across from CB#4 on East shore rd			24" DIA GRATE			
V-177	Behind CB#2 in grass on East Shore rd			22" x22" Grate			
V-178	Behind CB#2 in grass on East Shore rd			18" DIA GRATE			
V-179	Across from the Police station on Vineyard rd			Curb inelt			
VA-129	Lower Dr #1 across from	40 54.062 N	73 24.459 W	24" DIA GRATE			
VA-31	184 East Shore Road (Habor Hill Road Side)	40 54.0902 N	73 25.5616 W	Leaching System Connected			
VB-57	40 Baycrest	40, 54.223 N	73, 25.101 W	2X4 Catch Basin			
VB-58	24 Baycrest	40, 54.167 N	73, 25.113 W	2' Diameter Grate			
VB-59	32 Baycrest	40, 54.154 N	73, 25.124 W	2X4 Catch Basin			
VB-60	32 Baycrest	40, 54.154 N	73, 25.124W	2X4 Catch Basin			
VB-61	32 Baycrest	40, 54.153 N	73, 25.120 W	2X4 Catch Basin			
VB-65	44 Valley Drive	40, 54.139 N	73, 25.053 W	2X1 Basin			
VB-67	44 Valley Drive	40, 54.125 N	73, 25.025 W	2X4 Catch Basin			
VB-69	44 Valley Drive	40, 54.113 N	73, 25.026 W	2' Diameter Grate			
VB-73	54 Forest Avenue	40, 54.037 N	73, 24.937 W	2' Diameter Grate			
VB-74	54 Forest Avenue	40, 54.030 N	73, 24.934 W	2' Diameter Grate			
VB-75	60 Valley Road	40, 54.010 N	73, 24.991 W	2' Diameter Grate			
VB-76	12 Baycrest	40, 54.003 N	73, 25.041 W	2X4 Catch Basin			
VB-77	12 Baycrest	40, 54.000 N	73, 25.039 W	2X4 Catch Basin			
VB-78	10 Baycrest	40, 53.992 N	73, 25.074 W	2X4 Catch Basin			
VBH-133	Bay rd #154	40 54.076 N	73 24.323 W	type 1			
VBH-134	Bay rd storm pool discharge area	40 54.265 N	73 24.390 W	24" DIA GRATE			
VBH-135	Bay rd storm pool	40 54.260 N	73 24.393 W	24" DIA GRATE			
VBH-136	Shore rd #29	40 54.291 N	73 24.268 W	30" X 48" GRATE			
VBH-137	Shore rd corner soundview westside	40 54.287 N	73 24.266 W	type 1			
VBH-138	Shore rd #28 corner of soundview eastside	40 54.285 N	73 24.258 W	26" X 26" GRATE			
VBH-139	Across from #44 soundview	40 54.205 N	73 24.246 W	type 1			
VBH-140	Soundview #44	40 54.207 N	73 24.243 W	type 1			
VBH-141	Bay dr east corner of soundview	40 54.130 N	73 24.178 W	type 1			
VBH-142	Bay dr east corner of Highview #1	40 54.136 N	73 24.170 W	30" X 48" GRATE			
VBH-143	Bay dr east corner of Highview #2	40 54.137 N	73 24.169 W	30" X 48" GRATE			
VBH-144	Bay dr east corner of Highview #3	40 54.137 N	73 24.167 W	type 1			
VBH-148	122 Bay dr east #1	40 54.257 N	73 24.196 W	30 X 48 GRATE			
VBH-149	122 Bay dr east #2	40 54.255 N	73 24.195 W	30 X 48 GRATE			
VBH-150	125 Bay dr east across from 122 CB	40 54.259 N	73 24.190 W	30 X 48 GRATE			
VBH-151	1 Valley ct to the left	40 54.236 N	73 24.044 W	type 1			
VBH-152	1 Valley ct across from	40 54.233 N	73 24.044 W	type 1			
VBH-153	26 Valley dr middle of rd	40 54.226 N	73 24.026 W	30 X 48 GRATE			

VBH-154	26 Valley dr middle of rd	40 54.226 N	73 24.045 W	30 X 48 GRATE				
VBH-155	28 Valley dr end of rd	40 54.206 N	73 24.020 W	30 X 48 GRATE				
VBH-156	28 Valley dr end of rd	40 54.204 N	73 24.018 W	30 X 48 GRATE				
VBH-165	15 Hillside ct	40 54.178 N	73 24.089 W	24" DIA GRATE				
VBH-166	15 Hillside ct	40 54.178 N	73 24.088 W	30 X 48 GRATE				
VN-116	Taylor #32 near #37	40 53.007 N	73 24.720 W	30" X 4" GRATE				
VN-117	Taylor #35	40 54.000 N	73 24.714 W	30" X 48" GRATE				
VW-17	6 Woodland Drive (West Side)	40 54.1249 N	73 25.7241 W	Leaching System connected				
VW-18	Intersection of Woodland & Gromley Lane	40 54.1261 N	73 25.8048 W	Leaching System connection				
VW-180	Across from CB#22 on Hecksher Dr			open grate				
VW-181	Across from CB#2 on Gromely lane			open grate				
VW-19	Intersection of Woodland & Gromley Lane	40 54.1261 N	73 25.8048 W	Round inlet in center island, leaching system connected				
VW-20	17 Woodland Drive (West Side)	40 54.0843 N	73 25.8261 W	Leaching System Connected				
VW-21	19 Woodland Heckscher Drive& Woodland Drive (West Side)	40 54.0741 N	73 25.8267 W	Leaching System Connected				
VW-22	27 Heckscher Drive at Gormley Intersection	40 54.1783 N	73 25.8593 W	Leaching System Connected				
VW-23	32 Heckscher Drive	40 54.2051 N	73 25.8425 W	Leaching System Connected				
VW-24	32 Heckscher Drive	40 54.2051 N	73 25.8425 W	Leaching System Connected				
VW-30	Wincoma Drive west of Bay Intersection (south side)	40 54.1622 N	73 25.7063 W	Leaching System Connected				
VW-36	30 Heckscher dr	40 54.186 N	73 25.864 W	Leaching System Connected				
VW-42	299 Bay ave at intersection with Harbor View dr	40 54.166 N	73 25.625 W	Leaching System Connected				
VW-54	11 Beach Road	40, 54.247 N	73, 25.413 W	2' Diameter Grate				

V= Village owned	76
VW= Wincoma village Maintained	14
VB= Baycrest village Maintained	14
VN= Nathan Hale village Maintained	2
VBH= Bay Hills village Maintained	23
VA= Village Installed/Required Basin	2

Total Basins Subject to Village Inspection and Maintenance 131